46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

EJ67VHO

Volvo XC60 2.0 D5 PowerPulse R DESIGN Pro 5dr AWD Geartronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	22/11/2017
Year	2017
Mileage	84,977 Miles Warranted
Fuel Type	DIESEL
Colour	GREY
VIN	YV1UZ68BCJ1012309

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	3
Last service date	31/08/2023

Last service miles	54,549
MOT Due	21/11/2026
Gearbox	AUTOMATIC
Gears	8
Doors	5

£90 ADDITIONAL FEE
Last Service - 31.08.23 @ 54549 miles (3 main dealer services)

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	4.0mm
OSR	PIRELLI	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
Over 25mm Thru Paint



3: Wheel osr
Scratched
Over 50mm



4: Bumper Rear
Chipped
Multiple Chips



5: Boot Lid
Dented
With Paint Damage




6: Wheel nsr
Scratched
Over 50mm



7: Door nsf
Chipped
1 To 5



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Scratched
25 to 100mm Thru Paint



10: Bumper Front
Chipped
Multiple Chips



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		