46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY25XNO

BMW 2 Series 220i MHT M Sport 5dr DCT

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/04/2025	**Body Style**	Hatchback	**Last service miles**	6,911
Year	2025	**Keys**	2	**MOT Due**	29/04/2028
Mileage	7,055 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	HYBRID ELECTRIC	**Service documents**	Electronic / Online	**Gears**	7
Colour	BLACK	**Number of stamps**	1	**Doors**	5
VIN	WBA72BX0807R81483	**Last service date**	25/09/2026		

£90 ADDITIONAL FEE
Last Service - 25.09.2026 at 6911 miles (1 main dealer Services)

Tyres

NSF	BRIDGESTONE	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Cruise control
- Park assist camera
- Service indicator
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Partial leather seat trim
- Front parking sensor
- PAS
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking

Photos










GY25 XNO



BMW



Values since individual
0
Door open.



GHR 70s
2:03
Radio
Greatest Hits Radio 70
Greatest Hits Radio 70s
MEDIA
TEL
NAV
Home
20°
19°



PARKING
Rear
GHR 70s
2:03
Searching..
MEDIA
TEL
NAV
20°
19°


Tyre Pressure Monitor
Tyre Pressure Monitor active.
Engine oil level
Engine oil level OK.
Check Control
Door open.
Service
20°


OK Brake fluid
25/09/2027
OK Engine oil
25/09/2028, in 14000 mi
OK Vehicle check
25/09/2028, in 14000 mi
OK Gas pressure spring for bonr
OK Service:
On 25/09/2026, at 691
Service Partner: BMW 08
OK Service:
On 20/03/2025, at 5 m
Service Partner: BMW 22
20°
19°


GHR 70s
2:04
OK Service:
On 25/09/2026, at 6911 mi
Service Partner: BMW 08715
OK Service:
On 20/03/2025, at 5 mi
Service Partner: BMW 22041
MEDIA
TEL
NAV
19°



BMW







Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel nsf
Scratched
Up To 50mm



4: Wing nsf
Chipped
Edge Chip




5: Door nsr
Dented
Over 2 UpTo 10mm



6: Qtr Panel nsr
Chipped
1 To 5




7: Qtr Panel osr
Chipped
1 To 5



8: Door osr
Chipped
1 To 5



9: Door osf
Scratched
UpTo 25mm Thru Paint



10: Door osf
Chipped
Edge Chip



11: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK