46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HK19VGE

Audi Q3 35 TFSI Sport 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	18/03/2019
Year	2019
Mileage	77,823 Miles Warranted
Fuel Type	PETROL
Colour	WHITE
VIN	WAUZZZF35K1013050

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	8
Last service date	17/03/2026

Last service miles	69,850
MOT Due	17/03/2027
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
Last Service - 17.03.26 @ 69850 miles (8 main dealer services)

Tyres

NSF	SUNNY	5.0mm
NSR	RAPID	6.0mm
OSF	SUNNY	5.0mm
OSR	RAPID	6.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Digital radio
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Body coloured bumpers
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Service indicator
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- PAS
- Steering wheel mounted controls
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels

Photos




























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Back Cover osf
Scuffed
UpTo 25mm



2: Roof Lining
Soiled
Light



3: Bonnet
Chipped
1 To 5



4: Bumper Front
Chipped
1 To 5



5: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



6: Wheel nsf
Scratched
Up To 50mm



7: Screen Front
Chipped
Over 10mm



8: Door nsf
Chipped
1 To 5



9: Handle Outer nsr
Scratched (Painted)
Over 25mm Thru Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



13: Bumper Rear
Dented
With Paint Damage



14: B Post os
Dented
Between 10mm + 30mm



15: B Post ns
Dented
Between 10mm + 30mm



16: Door osr
Scratched
Over 25mm Thru Paint



17: Door osr
Dented
Between 10mm + 30mm



18: Door osf
Scratched
Over 25mm Thru Paint



19: Wing osf
Scratched
UpTo 25mm Thru Paint



20: Wheel osf
Scratched
Up To 50mm



21: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK