46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**EX62HGJ**

## Honda CR-V 2.0 i-VTEC EX 5dr Auto

nama GRADE 4

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | |
|---|---|
| **Reg. date** | 18/11/2012 |
| **Year** | 2012 |
| **Mileage** | 86,123 Miles Warranted |
| **Fuel Type** | PETROL |
| **Colour** | BROWN |
| **VIN** | SHSRE5890DU000729 |
| **Body Style** | Estate |

| | |
|---|---|
| **Keys** | 2 |
| **Service history** | Yes |
| **Service documents** | Service Book |
| **Number of stamps** | 12 |
| **Last service date** | 26/06/2026 |
| **Last service miles** | 84,668 |
| **MOT Due** | 13/07/2027 |

| | |
|---|---|
| **CAP Clean** | £6,775.00 |
| **CAP Average** | £5,925.00 |
| **CAP Below** | £5,075.00 |
| **Gearbox** | AUTOMATIC |
| **Gears** | 5 |
| **Doors** | 5 |

£90 ADDITIONAL FEE
LAST SERVICE 26/06/2026 @ 84,668 MILES (12 SERVICES)

### Tyres

| | | |
|---|---|---|
| **NSF** | DUNLOP | 4.0mm |
| **NSR** | BRIDGESTONE | 5.0mm |
| **OSF** | DUNLOP | 4.0mm |
| **OSR** | BRIDGESTONE | 5.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking

## Photos























**Eastbourne Car Auctions**


# Condition Check




## Damage Photos



1: Bonnet
Dented
2 Or Less UpTo 10mm



2: Bonnet
Scratched
Over 25mm Thru Paint



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Door nsf
Dented
With Paint Damage



8: Door nsr
Dented
With Paint Damage



9: Wheel nsr
Scratched
Over 50mm



10: Bumper Rear
Scratched
Over 100mm Thru Paint



11: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



12: Wheel osr
Scratched
Up To 50mm



13: Door osr
Scratched
Over 25mm Thru Paint



14: Door osf
Chipped
1 To 5



15: Door osf
Dented
Between 10mm + 30mm



16: Wing osf
Dented
Over 2 UpTo 10mm



17: Wheel osf
Scratched
Over 50mm

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |

| | | | |
|---|---|---|---|
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |