46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GD18RXP

Renault Kadjar 1.2 TCE Dynamique S Nav 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/08/2018	**Body Style**	Hatchback	**MOT Due**	20/10/2027
Year	2018	**Keys**	2	**Gearbox**	MANUAL
Mileage	47,593 Miles Warranted	**Service history**	Yes	**Gears**	6
Fuel Type	PETROL	**Service documents**	Printout	**Doors**	5
Colour	RED	**Number of stamps**	1		
VIN	VF1RFE00560926968	**Last service date**	14/08/2022		

£90 ADDITIONAL FEE
Last Service - 14.08.22 @ unknown miles (1 services)

Tyres

NSF	BUDGET	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	ATLAS	3.0mm
OSR	CONTINENTAL	3.0mm
Spare		


Features

- Bluetooth connection
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim

Photos
















Eastbourne Car Auctions


Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Door osr
Dented
2 Or Less UpTo 10mm



6: Wheel osr
Scratched
Over 50mm



7: Qtr Panel osr
Dented
Over 30mm



8: Bumper Rear
Cracked
Over 25mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Wheel nsr
Corroded
Light



11: Door nsf
Scratched
Over 25mm Thru Paint



12: Wheel nsf
Corroded
Light



13: Bonnet
Chipped
1 To 5



14: Bumper Front
Scratched
25 to 100mm Thru Paint



15: Roof
Chipped
1 To 5



16: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK