46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KY23FFU

Land Rover Range Rover Evoque 2.0 D200 Evoque Edition 5dr Auto

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	05/07/2023	**Body Style**	Estate	**Last service miles**	18,814
Year	2023	**Keys**	2	**MOT Due**	04/07/2027
Mileage	34,839 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	9
Colour	BLACK	**Number of stamps**	1	**Doors**	5
VIN	SALZA2AN7PH228446	**Last service date**	04/06/2026		

£90 ADDITIONAL FEE
Last Service - 04.06.25 @ 18814 miles (1 services)

Tyres

NSF	PIRELLI	5.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Traction control
- Alloy wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Electrically adjustable passenger seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Side airbags
- Leather seat trim


Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Seat Back Cover nsf
Scuffed
UpTo 25mm



2: Bonnet
Chipped
1 To 5



3: Bumper Front
Scratched
25 to 100mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



7: Door nsf
Scratched
Over 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint




9: Bumper Rear
Scratched
25 to 100mm Thru Paint




10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint




12: Door osr
Chipped
1 To 5



13: Door osf
Scratched
Over 25mm Thru Paint



14: Door osf
Dented
Between 10mm + 30mm



15: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Turbo Boosting	OK	No Excessive Smoking	OK
Parking Brake	OK		

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK