46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

PK64ENY

Citroen DS3 1.6 e-HDi Airdream DStyle Plus 3dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Reg. date	24/10/2014	**Body Style**	Hatchback	**Last service miles**	72,488
Year	2014	**Keys**	1	**MOT Due**	22/12/2026
Mileage	76,561 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	5
Colour	WHITE	**Number of stamps**	9	**Doors**	3
VIN	VF7SA9HPKEW661550	**Last service date**	24/07/2022		

£100 ADDITIONAL FEE
Last Service - 24.07.22 @ 72488 miles (9 services)
No V5 - Buyer to apply

Tyres

NSF	BUDGET	4.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	4.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features

- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Cloth seat trim
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos








HK64 ENY






12 · 52
101.40 MHz









HK64 ENY

Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Rusted
Over 5mm



4: Wheel osr
Corroded
Light



5: Boot Lid
Scratched
Over 25mm Thru Paint



6: Bumper Rear
Chipped
Multiple Chips



7: Bumper Rear
Scratched
Up To 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Door nsf
Poor Previous Repair
Paint Flake



10: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Scratched
25 to 100mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Roof
Poor Previous Repair
Paint Flake



15: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
		Steering	OK