46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OE19HVD

Jaguar XF 2.0i R-Sport 5dr Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/04/2019
Year	2019
Mileage	90,766 Miles Warranted
Fuel Type	PETROL
Colour	BLUE
VIN	SAJBB2AX8KCY81592

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	5
Last service date	23/10/2026

Last service miles	90,533
MOT Due	04/06/2027
Gearbox	AUTOMATIC
Gears	8
Doors	5

£90 ADDITIONAL FEE
Last Service - 23.10.26 @ 90533 miles (5 main dealer services) Tailgate out of line

Tyres

NSF	PIRELLI	4.0mm
NSR	PIRELLI	5.0mm
OSF	PIRELLI	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Fixed panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Alloy wheels
- Heated front seat
- Rear wiper
- Radio/CD
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Remote central locking

Photos











DE19 HVD





Press OK to clear
Please refuel
15:41
13°C


15:41
DAB RADIO
BBC Radio1
BBC Radio1
Source
Band
Favourites
Find
JADE plays Quickfire - can you beat her at naming things in a surprise category?!


15:41
SEATS
BBC Radio1
Temperature
Temperature


15:41
CAMERAS


15:41
NAVIGATION
Hello
Sign in to your account
LOW FUEL
Petrol stations nearby
20
Home
142 mi












Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Door nsf
Dented
Over 30mm



7: Door nsf
Chipped
1 To 5




8: Door nsr
Chipped
1 To 5



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Poor Previous Repair
Poor Paint




12: Other
N/A
N/A
Tailgate out of line




13: Qtr Panel osr
Chipped
Multiple Chips



14: Wheel osr
Scratched
Over 50mm



15: Door osf
Chipped
Edge Chip



16: Door osf
Chipped
1 To 5



17: Door osf
Dented
Between 10mm + 30mm



18: Roof
Chipped
1 To 5



19: Wheel osf
Scratched
Over 50mm



20: Wing osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK