46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY71AXK

Kia Xceed 1.5T GDi ISG 3 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/10/2021	**Body Style**	Hatchback	**Last service miles**	47,190
Year	2021	**Keys**	1	**MOT Due**	07/09/2027
Mileage	69,272 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	GREY	**Number of stamps**	1	**Doors**	5
VIN	U5YH5F15LML058721	**Last service date**	26/09/2024		

£100 ADDITIONAL FEE
Last Service - 26.09.24 @ 47190 miles (1 services)

Tyres

NSF	RAPID	4.0mm
NSR	RAPID	6.0mm
OSF	RAPID	4.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Alarm
- Alloy wheels
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos









TURBO
KIA



0 MPH




BBC Radio2
DAB/FM



Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Chipped
1 To 5



3: Wheel osr
Corroded
Light




4: Door osf
Chipped
1 To 5




5: Door osr
Chipped
1 To 5



6: Bumper Rear
Chipped
1 To 5



7: Door nsr
Chipped
1 To 5



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Dented
Between 10mm + 30mm



13: Bonnet
Chipped
1 To 5



14: Roof
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK