46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV16MMK

Nissan Qashqai 1.2 DiG-T Tekna [Non-Panoramic] 5dr Xtronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/06/2016
Year	2016
Mileage	68,720 Miles Warranted
Fuel Type	PETROL
Colour	GREY
VIN	SJNFEAJ11U1753411

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	8
Last service date	07/07/2026

Last service miles	67,097
MOT Due	09/07/2027
Gearbox	CVT
Gears	1
Doors	5

£90 ADDITIONAL FEE
Last Service - 07.07.26 @ 67097 miles (8 services) Noisy engine
Boot struts broken

Tyres

NSF	LAUFENN	6.0mm
NSR	ACCELERA	Damaged
OSF	BUDGET	6.0mm
OSR	ACCELERA	Damaged
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Door osr
Scratched
Over 25mm Thru Paint




4: Wheel osr
Corroded
Light



5: Bumper Rear
Chipped
Multiple Chips



6: Wheel nsr
Corroded
Light




7: Door nsr
Chipped
1 To 5



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Wheel nsf
Corroded
Light



10: Bumper Front
Scratched
UpTo 25mm Thru Paint



11: Bumper Front
Chipped
Multiple Chips



12: Bonnet
Chipped
1 To 5



13: Tyre nsr
Damaged
Replace



14: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	Fault	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		