46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**LV67FWA**

## Skoda Kodiaq 2.0 TSI SE L 4x4 5dr DSG [7 Seat]

nama GRADE 3

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | |
|---|---|
| **Reg. date** | 30/09/2017 |
| **Year** | 2017 |
| **Mileage** | 75,056 Miles Warranted |
| **Fuel Type** | PETROL |
| **Colour** | BLUE |
| **VIN** | TMBMD7NS2J8015823 |
| **Body Style** | Estate |

| | |
|---|---|
| **Keys** | 2 |
| **Service history** | Yes |
| **Service documents** | Printout |
| **Number of stamps** | 4 |
| **Last service date** | 05/07/2026 |
| **Last service miles** | 71,110 |
| **MOT Due** | Expired |

| | |
|---|---|
| **CAP Clean** | £11,200.00 |
| **CAP Average** | £9,975.00 |
| **CAP Below** | £8,775.00 |
| **Gearbox** | SEMI AUTO |
| **Gears** | 7 |
| **Doors** | 5 |

£90 ADDITIONAL FEE
MOT EXPIRED
MOT FAILURE - MUST BE TRANSPORTED OFF SITE
LAST SERVICE 05/07/2026 @ 71,110 MILES (4 SERVICES) Smoking

### Tyres

| | | |
|---|---|---|
| **NSF** | BRIDGESTONE | 6.0mm |
| **NSR** | BRIDGESTONE | 6.0mm |
| **OSF** | BRIDGESTONE | 6.0mm |
| **OSR** | BRIDGESTONE | 6.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Partial leather seat trim
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels

## Photos



































**Eastbourne Car Auctions**

# Condition Check





## Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint



5: Wheel nsf
Scratched
Up To 50mm




6: A Post ns
Chipped
1 To 5



7: Door nsf
Dented
2 Or Less UpTo 10mm



8: Door nsf
Chipped
1 To 5



9: Door nsr
Chipped
1 To 5



10: Qtr Panel nsr
Chipped
1 To 5



11: Wheel nsr
Corroded
Light



12: Boot Lid
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osr
Dented
2 Or Less UpTo 10mm



17: Door osf
Scratched
UpTo 25mm Thru Paint



18: Wing osf
Chipped
1 To 5

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | Fault |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |

| | | | |
|---|---|---|---|
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |