46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**LT15KFZ**

## Volvo XC90 2.0 D5 Momentum 5dr AWD Geartronic

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 26/06/2015 | **Body Style** | Estate | **Last service miles** | 73,056 |
| **Year** | 2015 | **Keys** | 2 | **MOT Due** | 02/05/2027 |
| **Mileage** | 97,526 Miles Warranted | **Service history** | Yes | **Gearbox** | AUTOMATIC |
| **Fuel Type** | DIESEL | **Service documents** | Printout | **Gears** | 8 |
| **Colour** | BLUE | **Number of stamps** | 9 | **Doors** | 5 |
| **VIN** | YV1LFA48CG1010755 | **Last service date** | 04/05/2024 | | |

£100 ADDITIONAL FEE
Throttle body replaced 12.01.26 @ 90192 miles
Last Service - 04.05.24 @ 73056 miles (9 services)
Sunroof does not open

### Tyres

| | | |
|---|---|---|
| **NSF** | BUDGET | 2.0mm |
| **NSR** | PIRELLI | 3.0mm |
| **OSF** | BUDGET | 3.0mm |
| **OSR** | PIRELLI | 2.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos

































**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Seat Base Cover osf
Scuffed
Over 25mm



2: Wheel osf
Scratched
Over 50mm



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
1 To 5



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Up To 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Bumper Rear
Chipped
1 To 5



9: Boot Lid
Dented
2 Or Less UpTo 10mm



10: Wheel nsr
Scratched
Over 50mm



11: Door nsf
Chipped
1 To 5



12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Bonnet
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Handle Inner osf
Damaged
Replace

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | Fault | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |