46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KY58YHW

Mercedes-Benz C Class C 200 CDI ELEGANCE

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/09/2008	**Keys**	2	**CAP Clean**	£1,925.00
Year	2008	**Service history**	Yes	**CAP Average**	£1,475.00
Mileage	76,141 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£1,050.00
Fuel Type	DIESEL	**Number of stamps**	13	**Gearbox**	AUTOMATIC
Colour	BLACK	**Last service date**	29/06/2026	**Gears**	5
VIN	WDD2040072A156833	**Last service miles**	74,690	**Doors**	4
Body Style	Saloon	**MOT Due**	01/09/2027		

£100 ADDITIONAL FEE
Last Service - 29.06.2026 at 74690 miles (13 Services)
Noisy when car is idling

Tyres

NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	KUMHO	5.0mm
Spare		

Features


- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Cloth seat trim
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Front parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Central locking
- Alloy wheels
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Remote central locking



Photos












Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Multiple Chips



4: Door osr
Chipped
1 To 5



5: Wheel osr
Corroded
Light



6: Qtr Panel osr
Chipped
1 To 5



7: Door osr
Chipped
Edge Chip



8: Bumper Rear
Poor Previous Repair
Paint Flake



9: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Corroded
Light



11: Door nsr
Chipped
1 To 5



12: Door nsr
Chipped
Edge Chip



13: Door nsf
Chipped
1 To 5



14: Door Mirror Glass ns
Broken
Replace



15: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



16: Wing nsf
Scratched
UpTo 25mm Thru Paint



17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Scratched
25 to 100mm Thru Paint



19: Bonnet
Chipped
1 To 5



20: Other
N/A
N/A



21: Other
N/A
N/A



22: Qtr Panel osr
Dented
Between 10mm + 30mm



23: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK