46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

PN13EXP

Honda Jazz 1.4 i-VTEC EX 5dr

Cat: S

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/03/2013	**Body Style**	Hatchback	**Last service miles**	21,982
Year	2013	**Keys**	2	**MOT Due**	25/02/2027
Mileage	69,112 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	5
Colour	RED	**Number of stamps**	1	**Doors**	5
VIN	SHHGG6780DU014377	**Last service date**	11/05/2016		

Category S Insurance Loss. Vehicle Structurally Damaged But Repairable-Insurer Decided Not to Repair
Last Service - 11.05.16 @ 21982 miles (1 services)
Trim from tailgate on the back seat

Tyres

NSF	HIFLY	3.0mm
NSR	FALKEN	5.0mm
OSF	FALKEN	3.0mm
OSR	FALKEN	4.0mm
Spare		

Features

- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Radio/CD
- Climate control
- Solid Paint
- Traction control
- Alloy wheels
- Body coloured bumpers
- Front electric windows
- ABS
- Central locking
- Electric door mirrors
- Rear electric windows
- Drivers airbag
- Remote central locking

Photos



















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Dented
With Paint Damage



6: Wheel osr
Scratched
Over 50mm




7: Boot Lid
Dented
With Paint Damage




8: Qtr Panel nsr
Dented
Over 30mm



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Scratched
UpTo 25mm Thru Paint



11: Door nsr
Chipped
1 To 5



12: Door nsf
Chipped
1 To 5



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Poor Previous Repair
Paint Flake



15: Bonnet
Chipped
Multiple Chips



16: Seat Back Cover osf
Holed
UpTo 3mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK