46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RX16XAO

Citroen C4 1.2 PureTech Flair 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	26/03/2016	**Body Style**	Hatchback	**Last service miles**	50,450
Year	2016	**Keys**	2	**MOT Due**	12/08/2027
Mileage	70,950 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	3	**Doors**	5
VIN	VF7NCHNZ6FY577752	**Last service date**	21/09/2022		

Last Service - 21.09.2022 at 50450 miles (3 Services)

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	4.0mm
OSF	WANLI	4.0mm
OSR	BUDGET	4.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos


















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip




5: Wheel osr
Scratched
Over 50mm



6: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



7: Boot Lid
Scratched
UpTo 25mm Thru Paint



8: Bumper Rear
Poor Previous Repair
Poor Colour



9: Qtr Panel nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Chipped
1 To 5



12: Door nsr
Scratched
UpTo 25mm Thru Paint



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
1 To 5



16: Roof
Dented
Hail - Moderate



17: C Post ns
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK