46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LG21ZYW

Kia Sportage 1.6 CRDi 48V ISG 2 5dr DCT Auto

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/03/2021
Year	2021
Mileage	42,946 Miles Warranted
Fuel Type	HYBRID ELECTRIC
Colour	GREY
VIN	U5YPH812VML035134
Body Style	Estate

Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	2
Last service date	03/03/2023
Last service miles	11,602
MOT Due	05/03/2027

CAP Clean	£10,100.00
CAP Average	£8,975.00
CAP Below	£7,850.00
Gearbox	SEMI AUTO
Gears	7
Doors	5

Last Service - 03.03.2023 at 11602 miles (2 Services)

Tyres

NSF	GT RADIAL	4.0mm
NSR	TRIANGLE	5.0mm
OSF	BUDGET	3.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels

Photos





























Eastbourne Car Auctions

Condition Check




Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Cracked
Over 25mm



3: Bumper Front Moulding
Broken
Replace




4: Wing nsf
Chipped
1 To 5



5: Wheel nsf
Scratched
Over 50mm



6: Flasher Side Repeater ns
Broken
Replace



7: Door nsf
Scratched
UpTo 25mm Thru Paint



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Door nsr
Dented
Between 10mm + 30mm



10: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Bumper Rear
Scratched
25 to 100mm Thru Paint



13: Tailgate
Scratched
Over 25mm Thru Paint



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Door osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel Moulding os
Scuffed (Unpainted)
UpTo 100mm



17: Door osf
Dented
With Paint Damage



18: Door Mirror Assy osf
Scuffed (Unpainted)
UpTo 100mm



19: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK