46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY70YTE

Mercedes-Benz C Class C200 AMG Line Edition 2dr 9G-Tronic

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	17/11/2020
Year	2020
Mileage	28,573 Miles Warranted
Fuel Type	HYBRID ELECTRIC
Colour	BLUE
VIN	W1K2053772G056564

Body Style	Coupe
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	2
Last service date	15/04/2025

Last service miles	23,199
MOT Due	16/11/2026
Gearbox	AUTOMATIC
Gears	9
Doors	2

£90 ADDITIONAL FEE
Last Service - 15.04.26 @ 23199 miles (2 services)

Tyres

NSF	WESTLAKE	2.0mm
NSR	WESTLAKE	3.0mm
OSF	WESTLAKE	3.0mm
OSR	WESTLAKE	3.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Body coloured bumpers
- Front armrest
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Air conditioning
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Radio/CD
- Climate control
- Metallic Paint
- Traction control
- Leather seat trim

Photos


























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



5: Wheel osr
Corroded
Light



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Wheel nsr
Corroded
Light



9: Door nsf
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5



11: Wheel nsf
Scratched
Up To 50mm



12: Bumper Front
Poor Previous Repair
Poor Paint



13: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK