46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**GU65HKO**

## Mazda 2 1.5 75 SE-L 5dr

nama GRADE 4

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 22/09/2015 | **Body Style** | Hatchback | **CAP Below** | £1,175.00 |
| **Year** | 2015 | **Keys** | 2 | **Gearbox** | MANUAL |
| **Mileage** | 161,968 Miles Warranted | **Service history** | None | **Gears** | 5 |
| | | **MOT Due** | 22/12/2026 | **Doors** | 5 |
| **Fuel Type** | PETROL | **CAP Clean** | £2,025.00 | | |
| **Colour** | WHITE | **CAP Average** | £1,600.00 | | |
| **VIN** | MMZDJ6HV51W121896 | | | | |

No Services History

### Tyres

| | | |
|---|---|---|
| **NSF** | DAVANTI | 6.0mm |
| **NSR** | DAVANTI | 3.0mm |
| **OSF** | DAVANTI | 2.0mm |
| **OSR** | DAVANTI | 3.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Central locking
- Cruise control
- Media storage
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Body coloured bumpers
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels

## Photos





























**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Bonnet
Poor Previous Repair
Paint Flake



2: Other
N/A
N/A
Headlights clouded



3: Fogdriving Lamp osf
Broken
Replace



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Bumper Front
Scratched
25 to 100mm Thru Paint



6: Wheel nsf
Scratched
Over 50mm



7: A Post ns
Chipped
1 To 5



8: Door nsf
Chipped
Edge Chip



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Scratched
Over 100mm Thru Paint



14: Boot Lid
Dented
With Paint Damage



15: Roof
Dented
Over 30mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Wheel osr
Corroded
Light



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Chipped
Edge Chip



20: Door osf
Dented
2 Or Less UpTo 10mm



21: Handle Outer osf
Scratched (Painted)
UpTo 25mm Thru Paint



22: Wheel osf
Scratched
Over 50mm



23: Wing osf
Chipped
1 To 5



24: Screen Front
Chipped
Over 10mm



25: Other
N/A
N/A
Steering wheel scuffed



26: Roof
Chipped
1 To 5

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| | | Steering | OK |