46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX20XCL

Audi Q3 35 TFSI Sport 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	07/03/2020	**Keys**	2	**CAP Clean**	£15,400.00
Year	2020	**Service history**	Yes	**CAP Average**	£14,100.00
Mileage	30,061 Miles Warranted	**Service documents**	Service Book	**CAP Below**	£12,800.00
Fuel Type	PETROL	**Number of stamps**	7	**Gearbox**	MANUAL
Colour	BLACK	**Last service date**	25/02/2026	**Gears**	6
VIN	WAUZZZF38L1046979	**Last service miles**	28,839	**Doors**	5
Body Style	Estate	**MOT Due**	06/03/2027		

£90 additional fee, LAST SERVICE 25-02-2026 @28839 MILES (7 SERVICES)

Tyres

NSF	HANKOOK	5.0mm
NSR	HANKOOK	5.0mm
OSF	HANKOOK	5.0mm
OSR	HANKOOK	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Scratched
Over 25mm Thru Paint



3: Bumper Rear
Scratched
25 to 100mm Thru Paint



4: Door nsr
Dented
With Paint Damage




5: Door nsf
Dented
Over 30mm



6: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK