46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GN14NKK

Peugeot 2008 1.6 e-HDi Allure 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/03/2014	**Colour**	WHITE	**MOT Due**	29/04/2027
Year	2014	**VIN**	VF3CU9HP0EY009752	**Gearbox**	MANUAL
Mileage	95,689 Miles Warranted	**Body Style**	Hatchback	**Gears**	5
		Keys	2	**Doors**	5
Fuel Type	DIESEL				

One key damaged
Central locking on key faulty

Tyres

NSF	JOYROAD	Damaged
NSR	RAPID	Damaged
OSF	JOYROAD	4.0mm
OSR	RAPID	4.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cruise control
- Service indicator
- Electric door mirrors
- Air conditioning
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Steering wheel mounted controls
- Fixed panoramic glass roof
- Folding rear seats
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Cloth seat trim
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels

Photos















11°c
14:53
DAB
11D
Smooth UK
On Air Now on Smooth: Paul Phear
Station
RDS
INFO


0
mph
095689
30.9


Condition Check



Damage Photos



1: Carpets Front
Torn
Over 10mm



2: Seat Back Cover osf
Scuffed
UpTo 25mm



3: Other
N/A
N/A
Carpet in boot damaged



4: Bonnet
Chipped
1 To 5



5: Other
N/A
N/A
Headlights clouded



6: Bumper Front
Scratched
25 to 100mm Thru Paint



7: Wheel nsf
Scratched
Over 50mm



8: Wing nsf
Dented
Between 10mm + 30mm



9: Door nsf
Dented
Over 30mm



10: Door nsr
Dented
Between 10mm + 30mm



11: Wheel nsr
Scratched
Over 50mm



12: Qtr Panel nsr
Dented
2 Or Less UpTo 10mm



13: Bumper Rear
Scratched
25 to 100mm Thru Paint



14: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



15: Boot Lid
Poor Previous Repair
Rippled UpTo 30%



16: Qtr Panel osr
Dented
Between 10mm + 30mm



17: Wheel osr
Scratched
Over 50mm



18: Door osr
Dented
Between 10mm + 30mm



19: Door osf
Chipped
Edge Chip



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wheel osf
Scratched
Over 50mm



22: Roof
Dented
Hail - Moderate



23: Tyre nsf
Damaged
Replace



24: Tyre nsr
Damaged
Replace

Interior

Carpet Condition	Poor	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK