46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY65WMM

Nissan Qashqai 1.2 DiG-T N-Tec+ 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/11/2015	**Body Style**	Hatchback	**Last service miles**	109,476
Year	2015	**Keys**	2	**MOT Due**	20/11/2026
Mileage	113,448 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	6
Colour	BLACK	**Number of stamps**	9	**Doors**	5
VIN	SJNFEAJ11U1555395	**Last service date**	05/06/2026		

Last Service - 05.06.20269 at 109476 miles (9 Services) Eml light is on car been plugged in and detected catalytic converter efficiency on Bank 1 is below the acceptable threshold.

Tyres

NSF	BUDGET	5.0mm
NSR	NEXEN	5.0mm
OSF	BUDGET	5.0mm
OSR	NEXEN	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim


Photos






























Eastbourne Car Auctions


Condition Check



Damage Photos



1: Carpets Front
Scuffed
Over 25mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
25 to 100mm Thru Paint




4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Chipped
1 To 5



7: Door nsf
Scratched
Over 25mm Thru Paint




8: Door nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Bumper Rear
Scratched
25 to 100mm Thru Paint



12: Boot Lid
Scratched
UpTo 25mm Thru Paint



13: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Scratched
Over 25mm Thru Paint



16: Door osf
Scratched
Over 25mm Thru Paint



17: Wing osf
Dented
Between 10mm + 30mm



18: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK