46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU16CXN

Mercedes-Benz A Class A200d AMG Line Premium 5dr Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	18/03/2016	**Colour**	WHITE	**MOT Due**	23/03/2027
Year	2016	**VIN**	WDD1760082J453468	**Gearbox**	AUTOMATIC
Mileage	82,668 Miles Warranted	**Body Style**	Hatchback	**Gears**	7
		Keys	2	**Doors**	5
Fuel Type	DIESEL				

Tyres

NSF	BUDGET	4.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	4.0mm
OSR	BUDGET	5.0mm
Spare		


Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos










FM radio
Heart



80L







Condition Check




Damage Photos



1: Wheel osf
Corroded
Light



2: Door osf
Chipped
1 To 5



3: Door osr
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Corroded
Light



7: Bumper Rear
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Door nsr
Chipped
1 To 5



10: Door nsf
Chipped
1 To 5



11: Wing nsf
Dented
Between 10mm + 30mm



12: Wheel nsf
Corroded
Light



13: Bumper Front
Chipped
Multiple Chips



14: Bonnet
Chipped
1 To 5



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
1 To 5



17: Seat Base Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK