46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV67NXU

Kia Niro 1.6 GDi PHEV 3 5dr DCT

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	20/02/2018	**Body Style**	Estate	**Last service miles**	61,216
Year	2018	**Keys**	2	**MOT Due**	19/02/2027
Mileage	63,196 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	8	**Doors**	5
VIN	KNACD81DVJ5113561	**Last service date**	10/02/2026		

£100 ADDITIONAL FEE
Last Service - 10.02.2026 at 61216 miles (8 main dealer Services) Type 2 and 3 pin charging cables in boot

Tyres

NSF	GT RADIAL	6.0mm
NSR	GT RADIAL	6.0mm
OSF	GT RADIAL	6.0mm
OSR	GT RADIAL	6.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Steel wheels
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Front parking sensor
- PAS
- Digital radio
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Wheel Trim nsf
Scratched
Over 50mm



4: Wing nsf
Chipped
1 To 5



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Door nsr
Scratched
Over 25mm Thru Paint




8: Wheel Trim nsr
Scratched
Over 50mm



9: Bumper Rear
Scratched
Up To 25mm Thru Paint




10: Boot Lid
Chipped
1 To 5



11: Spoiler Rear
Scratched (Painted)
Over 25mm Thru Paint



12: Qtr Panel osr
Chipped
1 To 5



13: Door osr
Chipped
1 To 5




14: Door osf
Scratched
UpTo 25mm Thru Paint



15: Door osf
Scratched
UpTo 25mm Thru Paint



16: Wing osf
Chipped
1 To 5



17: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK