46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

SM12FVL

Nissan Qashqai 2.0 N-Tec+ 5dr CVT

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	21/06/2012	**Body Style**	Hatchback	**Last service miles**	87,660
Year	2012	**Keys**	1	**MOT Due**	26/10/2027
Mileage	110,667 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	1
Colour	BLACK	**Number of stamps**	1	**Doors**	5
VIN	SJNFBAJ10U2562456	**Last service date**	22/11/2023		

£90 ADDITIONAL FEE
Last Service - 22.11.2023 at 87660 miles (1 Services)
Gearbox faulty (whinging)

Tyres

NSF	BUDGET	5.0mm
NSR	ROADSTONE	5.0mm
OSF	CONTINENTAL	Damaged
OSR	NEXEN	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Digital radio
- Fixed panoramic glass roof
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Cruise control
- Rear wiper
- Radio/CD
- Front fog lights
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Service indicator
- Body coloured bumpers
- Roof rails
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels


Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Poor Previous Repair
Paint Flake



3: Wheel nsf
Scratched
Over 50mm




4: Wing nsf
Scratched
UpTo 25mm Thru Paint




5: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



6: A Post ns
Scratched
Over 25mm Thru Paint



7: Door nsf
Poor Previous Repair
Rippled UpTo 30%



8: Door nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel Arch Extension ns
Broken
Replace



10: B Post ns
Scratched
Over 25mm Thru Paint



11: Wheel nsr
Scratched
Over 50mm



12: Bumper Rear
Poor Previous Repair
Paint Flake



13: Boot Lid
Scratched
UpTo 25mm Thru Paint




14: Qtr Panel osr
Dented
Between 10mm + 30mm




15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



17: Door osr
Dented
Over 30mm



18: Door osf
Dented
With Paint Damage



19: Wing osf
Poor Previous Repair
Poor Paint



20: Wheel osf
Scratched
Over 50mm



21: Screen Front
Chipped
UpTo 10mm



22: Aperture Seal osf
Broken
Replace



23: Other
N/A
N/A
Roof rails scratched



24: Seat Base Cover osf
Scuffed
Over 25mm



25: Fascia Trim
Damaged
Replace



26: Tyre osf
Damaged
Replace

Interior

Carpet Condition	-	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK