46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OY15KZR

Audi A6 2.0 TDI Ultra S Line 4dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/03/2015	**Body Style**	Saloon	**Last service miles**	114,464
Year	2015	**Keys**	2	**MOT Due**	08/03/2027
Mileage	120,605 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	GREY	**Number of stamps**	9	**Doors**	4
VIN	WAUZZZ4G1EN200580	**Last service date**	26/02/2026		

LAST SERVICE 26/02/2026 @ 114,464 MILES (9 SERVICES)

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	LAUFENN	5.0mm
OSF	BRIDGESTONE	6.0mm
OSR	LAUFENN	5.0mm
Spare		

Features


- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos
























Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm




2: Wing osf
Chipped
1 To 5



3: Door osf
Scratched
UpTo 25mm Thru Paint



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Door nsf
Dented
With Paint Damage



12: Wing nsf
Dented
With Paint Damage



13: Wheel nsf
Scratched
Over 50mm



14: Bumper Front
Scratched
Over 100mm Thru Paint



15: Bonnet
Chipped
Multiple Chips



16: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK