46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LD11JWG

Volvo XC60 D3 [163] SE 5dr Geartronic

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/03/2011	**Body Style**	Estate	**Last service miles**	81,403
Year	2011	**Keys**	2	**MOT Due**	24/02/2027
Mileage	103,240 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	12	**Doors**	5
VIN	YV1DZ5250B2208253	**Last service date**	10/03/2023		

Last Service - 10.03.2023 at 81403 miles (12 Services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Central locking
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Leather seat trim
- Park assist camera
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Curtain airbags
- Side airbags
- Alloy wheels

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Centre Console Front
Scuffed
Over 25mm



2: Bonnet
Chipped
1 To 5



3: Other
N/A
N/A
Headlights scratched



4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Other
N/A
N/A
Bonnet out line




6: Wing nsf
Chipped
1 To 5



7: Wheel nsf
Scratched
Up To 50mm



8: Door nsf
Scratched
Over 25mm Thru Paint



9: Door nsr
Chipped
1 To 5



10: Wheel nsr
Scratched
Over 50mm



11: Qtr Panel nsr
Chipped
1 To 5



12: Bumper Rear
Dented
With Paint Damage



13: Boot Lid
Chipped
1 To 5



14: Qtr Panel osr
Scratched
Over 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm




16: Door osr
Poor Previous Repair
Rippled UpTo 30%



17: Door osf
Chipped
Edge Chip



18: Door osf
Chipped
1 To 5



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK