46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LD19FLG

Ford Focus 1.0 EcoBoost 125 Titanium 5dr

nama GRADE 4

Inspection		Vehicle	
Serious Damage?	No	**VAT**	VAT Qualifying
		V5	Photocopy

Details

Reg. date	11/04/2019	**Keys**	1	**CAP Clean**	£5,000.00
Year	2019	**Service history**	Yes	**CAP Average**	£4,300.00
Mileage	72,821 Miles Warranted	**Service documents**	Printout	**CAP Below**	£3,650.00
Fuel Type	PETROL	**Number of stamps**	4	**Gearbox**	MANUAL
Colour	BLUE	**Last service date**	17/01/2025	**Gears**	6
VIN	WF0NXXGCHNKC39808	**Last service miles**	54,811	**Doors**	5
Body Style	Hatchback	**MOT Due**	02/03/2027		

Last Service - 17.01.2025 at 54811 miles (4 Services)
NO V5
2nd gear fault

Tyres

NSF	AVON	5.0mm
NSR	FALKEN	5.0mm
OSF	SAILUN	5.0mm
OSR	SAILUN	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Steering wheel mounted controls
- Front fog lights
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Cruise control
- PAS
- Digital radio
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Cloth seat trim
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking

Photos























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Other
N/A
N/A
Headlight scratched



4: Other
N/A
N/A
Bumper out of line



5: Wheel nsf
Scratched
Over 50mm



6: Wing nsf
Scratched
UpTo 25mm Thru Paint




7: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



8: Door nsf
Dented
Over 2 UpTo 10mm



9: Door nsf
Chipped
1 To 5



10: Door nsr
Dented
Over 30mm



11: Door nsr
Scratched
Over 25mm Thru Paint



12: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



13: Wheel nsr
Scratched
Over 50mm



14: Bumper Rear
Scratched
25 to 100mm Thru Paint



15: Qtr Panel osr
Scratched
Over 25mm Thru Paint



16: Qtr Panel osr
Dented
Between 10mm + 30mm



17: Door osr
Poor Previous Repair
Rippled UpTo 30%



18: Door osf
Chipped
Edge Chip



19: Door osf
Chipped
1 To 5



20: A Post os
Dented
Over 30mm



21: Wing osf
Dented
With Paint Damage



22: Wheel osf
Scratched
Over 50mm



23: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK