46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

G16SSP

DS Ds 4 1.6 BlueHDi Crossback 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	31/03/2018	**Colour**	BLACK	**Gearbox**	MANUAL
Year	2018	**VIN**	VF7NXBHZMHY530457	**Gears**	6
Mileage	114,549 Miles Warranted	**Body Style**	Hatchback	**Doors**	5
		Keys	2		
Fuel Type	Diesel				

Front suspension knocking

Tyres

NSF	SUNNY	Damaged
NSR	SUNNY	5.0mm
OSF	SUNNY	Damaged
OSR	SUNNY	5.0mm
Spare		


Features

- Bluetooth connection
- PAS
- Steering wheel mounted controls
- Electric door mirrors
- Front armrest
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Partial leather seat trim
- Cruise control
- Rear parking sensor
- Digital radio
- Front fog lights
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Navigation system
- Rear wiper
- Radio/CD
- Air conditioning
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Park assist camera
- Service indicator
- Body coloured bumpers
- Folding rear seats
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking


Photos
















Condition Check




Damage Photos



1: Tyre osf
Damaged
Replace



2: Tyre nsf
Damaged
Replace



3: Bonnet
Chipped
Multiple Chips




4: Bumper Front
Scratched
25 to 100mm Thru Paint



5: Wing nsf
Dented
With Paint Damage



6: Wheel nsf
Scratched
Over 50mm



7: Screen Front
Chipped
Over 10mm



8: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Poor Previous Repair
Poor Paint



10: Door nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Dented
With Paint Damage



14: Qtr Panel Arch Extension os
Broken
Replace



15: Wheel osr
Scratched
Over 50mm



16: Qtr Panel nsr
Dented
With Paint Damage



17: Qtr Panel osr
Dented
Over 30mm



18: Door osr
Scratched
Over 25mm Thru Paint



19: Door osf
Dented
2 Or Less UpTo 10mm



20: Door osf
Scratched
Over 25mm Thru Paint



21: Wing osf
Chipped
1 To 5



22: Wheel osf
Scratched
Over 50mm



23: Door Mirror Assy osf
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK