46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU13XXB

Toyota Auris 1.8 VVTi Hybrid Icon 5dr CVT Auto

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	09/07/2013	**Body Style**	Estate	**Last service miles**	121,379
Year	2013	**Keys**	2	**MOT Due**	08/07/2027
Mileage	121,427 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	HYBRID ELECTRIC	**Service documents**	Service Book	**Gears**	1
Colour	WHITE	**Number of stamps**	12	**Doors**	5
VIN	SB1ZS3JE80E032358	**Last service date**	22/10/2026		

Last Service - 22.10.2026 at 121379 miles (12 main dealer Services) EML light is on car has been plugged in and detects coolant pump B control circuit range / performance

Tyres

NSF	GOODYEAR	5.0mm
NSR	FIRESTONE	5.0mm
OSF	GOODYEAR	6.0mm
OSR	FIRESTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Alloy wheels
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front electric windows
- ABS
- Central locking

Photos



















Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: A Post os
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Dented
With Paint Damage



8: Qtr Panel nsr
Dented
With Paint Damage



9: Door nsr
Chipped
Edge Chip



10: Door nsf
Chipped
1 To 5



11: Door nsf
Chipped
Edge Chip




12: Wheel nsf
Scratched
Over 50mm



13: Bumper Front
Poor Previous Repair
Paint Flake



14: Bonnet
Chipped
Multiple Chips



15: Screen Front
Chipped
UpTo 10mm



16: Roof
Chipped
Over 5mm



17: Seat Back Cover osf
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	Fault
Airbag light illuminated	OK
ABS light illuminated	OK
Oil warning light illuminated	OK
Service indicator light illuminated	OK

Roof / sunroof	OK
Windows	OK
Sat nav	OK
Radio	OK
Steering	OK