46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GY24YSL

Kia Niro 1.6 GDi 127 Hybrid 3 5dr DCT

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	31/07/2024	**Body Style**	Estate	**Last service miles**	1,649
Year	2024	**Keys**	2	**MOT Due**	30/07/2027
Mileage	1,792 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	**Service documents**	Service Book	**Gears**	6
Colour	GREY	**Number of stamps**	2	**Doors**	5
VIN	KNACR81EVS5199474	**Last service date**	28/07/2026		

Last Service - 28.07.2026 at 1649 miles (2 main dealer Services)

Tyres

NSF	KUMHO	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	CONTINENTAL	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels

Photos











Classic FM










Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm




2: Wheel osr
Scratched
Over 50mm



3: Bumper Rear Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



4: Door nsr
Chipped
Edge Chip



5: Door nsf
Chipped
Edge Chip



6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Poor Previous Repair
Poor Paint

Interior

Carpet Condition	OK	**Upholstery Condition**	OK
Seat Condition	OK	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK