46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV17EOX

Audi A3 2.0 TDI S Line 2dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	24/06/2017	**Body Style**	Convertible	**Last service miles**	120,634
Year	2017	**Keys**	2	**MOT Due**	11/05/2027
Mileage	122,939 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	WHITE	**Number of stamps**	9	**Doors**	2
VIN	WAUZZZ8V1H1053987	**Last service date**	01/06/2026		

£90 ADDITIONAL FEE
LAST SERVICE 01/06/2026 @ 120,634 MILES (9 SERVICES)

Tyres

NSF	BRIDGESTONE	6.0mm
NSR	BRIDGESTONE	6.0mm
OSF	BRIDGESTONE	6.0mm
OSR	BRIDGESTONE	6.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Cruise control
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim
- Heated front seat
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Navigation system
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking


Photos








GV17 EOX




Capital DANCE
12:36
62040.2mi




Radio: DAB
BBC RadioSW
BBC RadioMusic
BBC WorldService
D1 National
Absolute Radio
Capital DANCE
Sport
Rock
Misc.
Rock
Pop



Audi
A3







Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wheel osr
Scratched
Over 50mm



3: Qtr Panel osr
Poor Previous Repair
Poor Paint



4: Bumper Rear
Dented
With Paint Damage



5: Wheel nsr
Scratched
Over 50mm



6: Wheel nsf
Scratched
Over 50mm



7: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		