46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**DX20ZKK**

## Nissan X-Trail 1.7 dCi Acenta Premium 5dr

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 09/03/2020 | **Body Style** | Estate | **MOT Due** | 08/05/2027 |
| **Year** | 2020 | **Keys** | 1 | **Gearbox** | MANUAL |
| **Mileage** | 62,638 Miles Warranted | **Service history** | Yes | **Gears** | 6 |
| **Fuel Type** | DIESEL | **Service documents** | Service Book | **Doors** | 5 |
| **Colour** | GREY | **Number of stamps** | 6 | | |
| **VIN** | JN1THAT32U0020575 | **Last service date** | 06/02/2026 | | |

Last Service - 06.02.2026 at unknown miles (6 Services )

### Tyres

| | | |
|---|---|---|
| **NSF** | MICHELIN | 5.0mm |
| **NSR** | BUDGET | 5.0mm |
| **OSF** | AUTOGREEN | 6.0mm |
| **OSR** | KUMHO | 6.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Electric door mirrors
- Air conditioning
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Radio/CD
- Opening panoramic glass roof
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Navigation system
- Rear wiper
- Body coloured bumpers
- Space saver spare wheel
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

## Photos


























**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Bonnet
Chipped
1 To 5



2: Bumper Front
Chipped
1 To 5



3: Bumper Front
Chipped
Over 5mm



4: A Post ns
Chipped
1 To 5



5: Door nsf
Dented
2 Or Less UpTo 10mm



6: Door nsf
Chipped
1 To 5



7: Door nsr
Dented
Between 10mm + 30mm



8: Door nsr
Chipped
Edge Chip



9: Other
N/A
N/A
Trims missing on the roof




10: Bumper Rear
Poor Previous Repair
Poor Paint




11: Bumper Reflector nsr
Broken
Replace




12: Qtr Panel osr
Chipped
1 To 5



13: Door osr
Chipped
Edge Chip



14: Door osr
Chipped
1 To 5



15: Door osr
Dented
2 Or Less UpTo 10mm



16: Door osf
Chipped
Edge Chip



17: Door osf
Dented
2 Or Less UpTo 10mm



18: Wing osf
Chipped
1 To 5



19: Screen Front
Chipped
UpTo 10mm



20: Roof
Chipped
1 To 5

## Interior

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**

**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**

**Additional fees may apply to some vendors.**

**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Parking Brake | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |