46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

KV14YBC

Audi Q5 2.0 TDI Quattro S Line 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	05/06/2014	**Body Style**	Estate	**Last service miles**	68,767
Year	2014	**Keys**	2	**MOT Due**	07/06/2027
Mileage	125,776 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	5	**Doors**	5
VIN	WAUZZZ8RXEA124179	**Last service date**	06/07/2020		

Last Service - 06.07.20 @ 68767 miles (5 main dealer services) Engine oil pressure low

Tyres

NSF	NEXEN	3.0mm
NSR	BUDGET	3.0mm
OSF	NEXEN	3.0mm
OSR	BUDGET	3.0mm
Spare		

Features

- Bluetooth connection
- Rear wiper
- Body coloured bumpers
- Air conditioning
- Height adjustable drivers seat
- Steering wheel rake adjustment
- ABS
- Passenger airbag
- Alarm
- Cruise control
- Steering wheel mounted controls
- Electric door mirrors
- Climate control
- Rear armrest
- Steering wheel reach adjustment
- Curtain airbags
- Rear airbags
- Remote central locking
- PAS
- Trip computer
- Front fog lights
- Front electric windows
- Rear electric windows
- Metallic Paint
- Drivers airbag
- Traction control
- Leather seat trim
- Rear parking sensor
- Radio/CD
- Roof rails
- Front head restraints
- Rear headrests
- 3x3 point rear seat belts
- Isofix child seat anchor points
- Tyre pressure monitor
- Alloy wheels

Photos


















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Other
N/A
N/A



4: Door osf
Chipped
Multiple Chips



5: Door osr
Poor Previous Repair
Poor Paint



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Scratched
25 to 100mm Thru Paint



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Door nsr
Chipped
Edge Chip



11: Door nsr
Chipped
1 To 5




12: Door nsf
Chipped
Multiple Chips



13: Wheel nsf
Scratched
Over 50mm



14: Wing nsf
Chipped
1 To 5




15: Bumper Front
Poor Previous Repair
Poor Paint



16: Bonnet
Chipped
1 To 5



17: Screen Front
Chipped
UpTo 10mm



18: Roof
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK