46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GL14EOZ

Audi A4 2.0 TDI 150 S Line 4dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/05/2014	**Body Style**	Saloon	**Last service miles**	86,281
Year	2014	**Keys**	2	**MOT Due**	24/06/2027
Mileage	113,523 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	7	**Doors**	4
VIN	WAUZZZ8K9EA128808	**Last service date**	31/05/2024		

£90 ADDITIONAL FEE
Last Service - 31.05.24 @ 86281 miles (7 services)

Tyres

NSF	BUDGET	5.0mm
NSR	PIRELLI	5.0mm
OSF	BUDGET	5.0mm
OSR	PIRELLI	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Central locking
- Alloy wheels
- Cruise control
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Remote central locking
- Front parking sensor
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos






















Eastbourne Car Auctions

Condition Check



Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Door osr
Chipped
Edge Chip



6: Wheel osr
Scratched
Over 50mm



7: Bumper Rear
Dented
With Paint Damage



8: Lamp osr
Broken
Replace



9: Door nsr
Chipped
1 To 5



10: Wing nsf
Dented
Over 30mm



11: Wheel nsf
Scratched
Over 50mm



12: Bumper Front
Poor Previous Repair
Paint Flake



13: Bonnet
Chipped
Multiple Chips



14: Screen Front
Chipped
UpTo 10mm



15: Sunvisor ns
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK