46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GR21HDJ

BMW X3 xDrive30d MHT M Sport 5dr Auto

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	29/03/2021	**Body Style**	Estate	**Last service miles**	42,838
Year	2021	**Keys**	2	**MOT Due**	28/03/2027
Mileage	54,365 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	ELECTRIC DIESEL	**Service documents**	Printout	**Gears**	8
Colour	GREY	**Number of stamps**	2	**Doors**	5
VIN	WBAUZ96010N080332	**Last service date**	07/10/2025		

£90 ADDITIONAL FEE
LAST SERVICE 07/10/2025 @ 42,838 MILES (2 SERVICES)

Tyres

NSF	PIRELLI	6.0mm
NSR	PIRELLI	4.0mm
OSF	PIRELLI	6.0mm
OSR	PIRELLI	4.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Electric sunroof
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Cruise control
- Park assist camera
- Radio/CD
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos









































Eastbourne Car Auctions


Condition Check



Damage Photos



1: Door osf
Chipped
Edge Chip



2: Door osr
Scratched
UpTo 25mm Thru Paint



3: Wheel osr
Scratched
Up To 50mm



4: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



5: Bumper Rear
Scratched
25 to 100mm Thru Paint



6: Door nsr
Dented
Between 10mm + 30mm



7: Wing nsf
Chipped
1 To 5



8: Bumper Front
Scratched
25 to 100mm Thru Paint



9: Bonnet
Chipped
1 To 5



10: Screen Front
Chipped
UpTo 10mm



11: Door osr
Dented
Between 10mm + 30mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		