46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**MW22AOL**

## Volkswagen Tiguan Allspace 2.0 TDI R-Line 5dr DSG

nama GRADE 3

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 24/05/2022 | **Body Style** | Estate | **Last service miles** | 44,186 |
| **Year** | 2022 | **Keys** | 2 | **MOT Due** | 30/07/2027 |
| **Mileage** | 50,786 Miles Warranted | **Service history** | Yes | **Gearbox** | SEMI AUTO |
| **Fuel Type** | DIESEL | **Service documents** | Printout | **Gears** | 7 |
| **Colour** | WHITE | **Number of stamps** | 3 | **Doors** | 5 |
| **VIN** | WVGZZZ5NZNM098868 | **Last service date** | 13/05/2026 | | |

£90 ADDITIONAL FEE
Last Service - 13.05.26 @ 44186 miles (3 main dealer services)

### Tyres

| | | |
|---|---|---|
| **NSF** | CONTINENTAL | Damaged |
| **NSR** | MICHELIN | 3.0mm |
| **OSF** | MICHELIN | 5.0mm |
| **OSR** | CONTINENTAL | 2.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Air conditioning
- Cruise control
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Front parking sensor
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Heated front seat
- Telephone
- Electric sunroof
- Electrically adjustable passenger seat
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Rear electric windows
- Drivers airbag
- Central locking
- Rear headrests
- Passenger airbag
- Remote central locking

## Photos









































**Eastbourne Car Auctions**

# Condition Check




## Damage Photos




1: Wheel osf
Scratched
Over 50mm



2: Door osf
Chipped
1 To 5



3: Door osf
Dented
Between 10mm + 30mm



4: Wheel osr
Corroded
Light



5: Bumper Rear
Chipped
Multiple Chips



6: Wheel nsr
Corroded
Light




7: Door Mirror Assy nsf
Broken
Replace



8: Wheel nsf
Scratched
Over 50mm



9: Bumper Front
Poor Previous Repair
Paint Flake



10: Screen Front
Cracked
Replace




11: Tyre nsf
Damaged
Replace

**Interior**

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**
**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**
**Additional fees may apply to some vendors.**
**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |

| | | | |
|---|---|---|---|
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |