46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GV17UDE

Kia Sportage 2.0 CRDi KX-3 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/06/2017
Year	2017
Mileage	85,094 Miles Warranted
Fuel Type	DIESEL
Colour	RED
VIN	U5YPH813NGL196114

Body Style	Estate
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	9
Last service date	23/10/2025

Last service miles	76,115
MOT Due	Expired
Gearbox	MANUAL
Gears	6
Doors	5

£90 ADDITIONAL FEE
Last Service - 23.10.25 @ 76115 miles (9 main dealer services)

Tyres

NSF	MAXXIS	3.0mm
NSR	MATADOR	3.0mm
OSF	MAXXIS	3.0mm
OSR	BRIDGESTONE	4.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos

















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Wheel osr
Corroded
Light



5: Door osr
Dented
Over 30mm



6: Bumper Rear
Chipped
Multiple Chips



7: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



8: Bumper Rear
Scratched
Up To 25mm Thru Paint



9: Wheel nsr
Corroded
Light



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Door nsr
Dented
Between 10mm + 30mm



12: Wheel nsf
Corroded
Light



13: Bumper Front
Scratched
25 to 100mm Thru Paint



14: Screen Front
Chipped
UpTo 10mm



15: Lamp nsr
Broken
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK