46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

LS21GXP

Abarth 595 1.4 T-Jet 145 3dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	30/04/2021	**Body Style**	Hatchback	**Last service miles**	26,822
Year	2021	**Keys**	2	**MOT Due**	29/04/2027
Mileage	71,974 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	GREY	**Number of stamps**	2	**Doors**	3
VIN	ZFA3120000JF08970	**Last service date**	19/12/2023		

£90 ADDITIONAL FEE
Last Service - 19.12.23 @ 26822 miles (2 services)
Noisy gearbox

Tyres

NSF	GOODYEAR	5.0mm
NSR	CONTINENTAL	5.0mm
OSF	GOODYEAR	5.0mm
OSR	CONTINENTAL	5.0mm
Spare		

Features

- Bluetooth connection
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Passenger airbag
- Cloth seat trim
- Rear parking sensor
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Side airbags
- Alloy wheels
- Rear wiper
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Central locking


Photos










LS21 GXP






0
MPH
71974 mi
10 °C


BBC Radio2



248


ABARTH


www.ebca.co.uk



Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Wheel osr
Scratched
Over 50mm



5: Fog Lamp osr
Broken
Replace



6: Bumper Rear
Chipped
1 To 5



7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Chipped
Edge Chip




9: Wheel nsf
Scratched
Over 50mm



10: Bumper Front
Scratched
25 to 100mm Thru Paint



11: Bonnet
Chipped
1 To 5



12: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK