46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GN19NBA

Toyota Corolla 2.0 VVT-i Hybrid Design 5dr CVT

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	01/03/2019	**Body Style**	Hatchback	**Last service miles**	45,107
Year	2019	**Keys**	2	**MOT Due**	28/02/2027
Mileage	48,774 Miles Warranted	**Service history**	Yes	**Gearbox**	CVT
Fuel Type	HYBRID ELECTRIC	**Service documents**	Service Book	**Gears**	1
Colour	RED	**Number of stamps**	6	**Doors**	5
VIN	SB1K53BEX0E002057	**Last service date**	11/02/2026		

Last Service - 11.02.2026 at 45107 miles (6 Services)

Tyres

NSF	GOODYEAR	Damaged
NSR	GOODYEAR	5.0mm
OSF	GOODYEAR	5.0mm
OSR	GOODYEAR	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels


Photos



















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Door osr
Scratched
UpTo 25mm Thru Paint



3: Qtr Panel osr
Chipped
1 To 5



4: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



5: Wheel nsf
Corroded
Light



6: Bumper Front
Poor Previous Repair
Poor Paint



7: Bonnet
Chipped
1 To 5



8: Tyre nsf
Damaged
Replace



9: Door nsf
Dented
2 Or Less UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK