46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

# VEHICLE INSPECTION REPORT

**OV69NJN**

## Volkswagen Arteon 2.0 TSI R-Line 5dr DSG

nama GRADE 2

### Inspection

| | |
|---|---|
| **Serious Damage?** | No |

### Vehicle

| | |
|---|---|
| **VAT** | Margin |
| **V5** | Present |

### Details

| | | | | | |
|---|---|---|---|---|---|
| **Reg. date** | 31/10/2019 | **Keys** | 2 | **CAP Clean** | £13,300.00 |
| **Year** | 2019 | **Service history** | Yes | **CAP Average** | £12,150.00 |
| **Mileage** | 51,893 Miles Warranted | **Service documents** | Printout | **CAP Below** | £11,050.00 |
| **Fuel Type** | PETROL | **Number of stamps** | 7 | **Gearbox** | SEMI AUTO |
| **Colour** | GREY | **Last service date** | 14/07/2026 | **Gears** | 7 |
| **VIN** | WVWZZZ3HZLE002056 | **Last service miles** | 45,424 | **Doors** | 5 |
| **Body Style** | Hatchback | **MOT Due** | 01/11/2027 | | |

Last Service - 14.07.26 @ 45424 miles (7 services (6 main dealer))
Mechatronic assembly replaced by dealer 14.07.26 @ 45424 miles

### Tyres

| | | |
|---|---|---|
| **NSF** | FARROAD | 6.0mm |
| **NSR** | FARROAD | 6.0mm |
| **OSF** | FARROAD | 6.0mm |
| **OSR** | FARROAD | 6.0mm |
| **Spare** | | |

## Features

- Bluetooth connection
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Cruise control
- Park assist camera
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Front parking sensor
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Heated front seat
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking

## Photos





















**Eastbourne Car Auctions**

# Condition Check




## Damage Photos



1: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



2: Wheel nsr
Corroded
Light



3: Qtr Panel nsr
Chipped
1 To 5



4: Door nsr
Chipped
1 To 5



5: Wheel nsf
Scratched
Up To 50mm



6: Bumper Front
Chipped
Multiple Chips



7: Bonnet
Chipped
1 To 5



8: Screen Front
Chipped
UpTo 10mm

## Interior

| | | | |
|---|---|---|---|
| **Carpet Condition** | Average | **Upholstery Condition** | Average |
| **Seat Condition** | Average | **Odour** | No |

## Vehicle Inspection Report

**Disclaimer**

**Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.**

**Additional fees may apply to some vendors.**

**Please note buyers rate increase from 01/01/2025**

| | | | |
|---|---|---|---|
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| Parking Brake | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | Service indicator light illuminated | OK |
| ABS light illuminated | OK | | |
| Windows | OK | Radio | OK |
| Sat nav | OK | Steering | OK |