46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX71YZM

Dacia Duster 1.0 TCe 90 Prestige 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	18/09/2021
Year	2021
Mileage	36,625 Miles Warranted
Fuel Type	PETROL
Colour	WHITE
VIN	VF1HJD20768169459

Body Style	Hatchback
Keys	2
Service history	Yes
Service documents	Service Book
Number of stamps	3
Last service date	26/08/2025

Last service miles	32,345
MOT Due	17/09/2027
Gearbox	MANUAL
Gears	6
Doors	5

£100 ADDITIONAL FEE
26/08/2025 @ 32,345 MILES (3 SERVICES)

Tyres

NSF	NEXEN	5.0mm
NSR	NEXEN	6.0mm
OSF	NEXEN	5.0mm
OSR	CONTINENTAL	Damaged
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Solid Paint
- Traction control
- Cloth seat trim
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos












Signal lost
Menu
Signal lost

Signal lost
List
Presets
Options





Condition Check



Damage Photos



1: Wing osf
Dented
Between 10mm + 30mm



2: Door osf
Chipped
1 To 5



3: Door osf
Chipped
Edge Chip



4: Qtr Panel osr
Chipped
Edge Chip



5: Handle Outer nsf
Scratched (Painted)
UpTo 25mm Thru Paint



6: Wing nsf
Scratched
Over 25mm Thru Paint



7: Bumper Front
Scratched
25 to 100mm Thru Paint



8: Bumper Front
Chipped
1 To 5



9: Wheel nsf
Scratched
Up To 50mm



10: Bonnet
Chipped
1 To 5



11: Tyre osr
Damaged
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK