46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

PL16PXS

Hyundai Santa Fe 2.2 CRDi Blue Drive Wiggins Ed 5dr Auto [7 Seats]

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/08/2016	**Body Style**	Estate	**Last service miles**	86,136
Year	2016	**Keys**	2	**MOT Due**	11/09/2027
Mileage	92,107 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	DIESEL	**Service documents**	Service Book	**Gears**	6
Colour	BLUE	**Number of stamps**	8	**Doors**	5
VIN	KMHSW81XSGU673529	**Last service date**	09/09/2025		

Last Service - 09.09.2025 at 86136 miles (8 Services) Gear linkage stiff

Tyres

NSF	KUMHO	5.0mm
NSR	KUMHO	5.0mm
OSF	KUMHO	5.0mm
OSR	DAVANTI	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Rear wiper
- Electric door mirrors
- Air conditioning
- Cruise control
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Electrically adjustable drivers seat
- Front parking sensor
- PAS
- Digital radio
- Opening panoramic glass roof
- Electrically adjustable passenger seat
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Roof rails
- Folding rear seats
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Leather seat trim
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Central locking

Photos

























Eastbourne Car Auctions

Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bumper Front Moulding
Broken
Replace



4: Bumper Front
Scratched
25 to 100mm Thru Paint




5: Wing nsf
Chipped
1 To 5



6: Wheel nsf
Scratched
Over 50mm



7: Door Mirror Assy nsf
Broken
Replace



8: Door nsf
Scratched
UpTo 25mm Thru Paint



9: Door nsr
Scratched
Over 25mm Thru Paint



10: Wheel nsr
Scratched
Over 50mm



11: Door nsr
Dented
Between 10mm + 30mm



12: Qtr Panel nsr
Dented
With Paint Damage



13: Bumper Rear
Dented
With Paint Damage



14: Wheel osr
Scratched
Over 50mm



15: Door osr
Chipped
1 To 5



16: Door osf
Dented
Between 10mm + 30mm



17: Door osf
Chipped
Edge Chip



18: Door osf
Scratched
UpTo 25mm Thru Paint



19: Wing osf
Chipped
1 To 5



20: Wheel osf
Scratched
Over 50mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	Fault
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	Fault
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		