46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

HG18CSO

Audi A3 1.5 TFSI Black Edition 4dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	10/05/2018
Year	2018
Mileage	98,860 Miles Warranted
Fuel Type	PETROL
Colour	GREY
VIN	WAUZZZ8V7J1059377

Body Style	Saloon
Keys	2
Service history	Yes
Service documents	Printout
Number of stamps	9
Last service date	27/09/2025

Last service miles	90,186
MOT Due	09/05/2027
Gearbox	MANUAL
Gears	6
Doors	4

£90 ADDITIONAL FEE
CAMBELT REPLACED 13/04/2023
LAST SERVICE 27/09/2025 @ 90,186 MILES (9 SERVICES) Intermittent rattle on start up

Tyres

NSF	BUDGET	5.0mm
NSR	BRIDGESTONE	5.0mm
OSF	BRIDGESTONE	5.0mm
OSR	BRIDGESTONE	5.0mm
Spare		

Features

- Bluetooth connection
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Alloy wheels
- Cruise control
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Cloth seat trim
- Rear parking sensor
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Leather seat trim

Photos









HG18 CSO


17:43
6.9mpg
98860
2856.8
+11.5%




Radio: FM/DAB
Hits Radio 90s
Hits Radio Pride
Hits Radio Sussx
KISS
KISS DANCE
KISSTORY
20.0°
20.0°










Condition Check




Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Dented
With Paint Damage



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Door osr
Chipped
Edge Chip



7: Bumper Rear
Scratched
Over 100mm Thru Paint



8: Boot Lid
Scratched
UpTo 25mm Thru Paint



9: Wheel nsr
Scratched
Over 50mm



10: Door nsr
Chipped
Edge Chip



11: Wheel nsf
Scratched
Over 50mm



12: Wing nsf
Scratched
Over 25mm Thru Paint



13: Bonnet
Chipped
1 To 5



14: Bumper Front
Chipped
Multiple Chips



15: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	Fault
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK