46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

NV72CLU

MG Mg Zs EXCLUSIVE T-GDI

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	09/01/2023	**Body Style**	Hatchback	**Last service miles**	18,212
Year	2023	**Keys**	2	**MOT Due**	25/01/2027
Mileage	19,479 Miles Warranted	**Service history**	Yes	**Gearbox**	AUTOMATIC
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	ORANGE	**Number of stamps**	1	**Doors**	5
VIN	LSJW74C96NZ283562	**Last service date**	22/04/2026		

£90 ADDITIONAL FEE
Last Service - 22.04.26 @ 18212 miles (1 service)

Tyres

NSF	HANKOOK	5.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	5.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Steering wheel mounted controls
- Front fog lights
- Folding rear seats
- Height adjustable drivers seat
- Steering wheel reach adjustment
- Drivers airbag
- Traction control
- Alloy wheels
- Cruise control
- PAS
- Digital radio
- Roof rails
- Front armrest
- Rear electric windows
- Metallic Paint
- Isofix child seat anchor points
- Central locking
- Heated front seat
- Rear parking sensor
- Body coloured bumpers
- Air conditioning
- Front electric windows
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Remote central locking
- Navigation system
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Front head restraints
- Steering wheel rake adjustment
- ABS
- Side airbags
- Leather seat trim

Photos









NV72 CLD










MGZS







09:54
A/C
Unnamed road
Eastbourne
2D
A2280
Select as Destination




HVAC

Condition Check



Damage Photos



1: Wing osf
Chipped
1 To 5



2: Door osf
Chipped
Edge Chip




3: Door osr
Chipped
1 To 5



4: Door osr
Chipped
Edge Chip



5: Door nsr
Chipped
Edge Chip




6: Door nsr
Chipped
1 To 5



7: Door nsf
Chipped
Edge Chip



8: Door nsf
Chipped
1 To 5



9: Bumper Front
Chipped
1 To 5



10: Carpets Front
Scuffed
Over 25mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
		Clutch Slip Test from Static	OK
		Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK