46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GU16TUO

Audi Q5 2.0 TDI [190] Quattro S Line Plus 5dr

nama GRADE 2

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	25/03/2016	**Body Style**	Estate	**Last service miles**	48,010
Year	2016	**Keys**	2	**MOT Due**	30/03/2027
Mileage	56,978 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	DIESEL	**Service documents**	Printout	**Gears**	6
Colour	BLACK	**Number of stamps**	5	**Doors**	5
VIN	WAUZZZ8R6GA108144	**Last service date**	25/03/2024		

£90 ADDITIONAL FEE
LAST SERVICE 25/036/2024 @ 48,010 MILES (5 SERVICES)

Tyres

NSF	ROTALLA	4.0mm
NSR	AVON	5.0mm
OSF	ROTALLA	4.0mm
OSR	AVON	5.0mm
Spare		

Features

- Bluetooth connection
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Cruise control
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Navigation system
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking

Photos















767




Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osf
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip



4: Door osr
Chipped
1 To 5



5: Other
N/A
N/A



6: Bumper Rear
Dented
With Paint Damage



7: Wheel nsr
Scratched
Over 50mm



8: Door nsf
Dented
Between 10mm + 30mm



9: Wheel nsf
Scratched
Over 50mm



10: Bonnet
Chipped
1 To 5



11: Screen Front
Chipped
UpTo 10mm

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	Fault
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK