46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

YG61LVR

Ford Fiesta 1.6 TDCi [95] Titanium 5dr

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	03/10/2011	**Body Style**	Hatchback	**MOT Due**	26/11/2026
Year	2011	**Service history**	Yes	**Gearbox**	MANUAL
Mileage	66,182 Miles Warranted	**Service documents**	Printout	**Gears**	5
Fuel Type	DIESEL	**Number of stamps**	4	**Doors**	5
Colour	BLACK	**Last service date**	19/11/2024		
VIN	WF0JXXWPJJBS18290	**Last service miles**	60,983		

Last Service - 19.11.2024 at 60983 miles (4 Services)
Timing Belt + Water Pump Replaced 18.11.2024 @ 60978 Miles

Tyres

NSF	BARUM	4.0mm
NSR	UNIROYAL	5.0mm
OSF	BARUM	3.0mm
OSR	NANKANG	4.0mm
Spare		

Features

- Bluetooth connection
- Air conditioning
- Front head restraints
- Metallic Paint
- Isofix child seat anchor points
- Leather seat trim
- Radio/CD
- Climate control
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Alloy wheels
- Body coloured bumpers
- Folding rear seats
- Steering wheel rake adjustment
- ABS
- Alarm
- Electric door mirrors
- Front electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Remote central locking

Photos













SONY
INFO
CLOCK
RADIO





Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Wing osf
Chipped
1 To 5



3: Door osf
Chipped
1 To 5



4: Door osf
Chipped
Edge Chip



5: Door osr
Chipped
1 To 5



6: Door osr
Chipped
Edge Chip



7: Qtr Panel osr
Dented
2 Or Less UpTo 10mm



8: Qtr Panel osr
Chipped
1 To 5




9: Wheel osr
Scratched
Over 50mm



10: Bumper Rear
Chipped
Multiple Chips



11: Qtr Panel nsr
Chipped
1 To 5



12: Qtr Panel nsr
Dented
Between 10mm + 30mm



13: Wheel nsr
Scratched
Over 50mm



14: Qtr Panel nsr
Chipped
Edge Chip



15: Door nsr
Scratched
Over 25mm Thru Paint



16: Door nsf
Chipped
1 To 5




17: Wheel nsf
Scratched
Over 50mm



18: Bumper Front
Chipped
Multiple Chips



19: Bonnet
Chipped
1 To 5



20: Screen Front
Chipped
UpTo 10mm



21: Roof
Poor Previous Repair
Poor Paint



22: Boot Lid
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	Fault
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK
Windows	OK	Radio	OK
		Steering	OK