46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

GX72XGY

Audi A3 40 TFSI e S Line 5dr S Tronic

nama GRADE 3

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	15/10/2022	**Body Style**	Hatchback	**Last service miles**	34,030
Year	2022	**Keys**	2	**MOT Due**	03/07/2027
Mileage	35,694 Miles Warranted	**Service history**	Yes	**Gearbox**	SEMI AUTO
Fuel Type	HYBRID ELECTRIC	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	4	**Doors**	5
VIN	WAUZZZGY4PA031279	**Last service date**	06/08/2026		

£90 ADDITIONAL FEE
Last Service - 06.08.26 @ 34030 miles (4 main dealer services)
Type 2 and 3 pin charging cables

Tyres

NSF	MICHELIN	6.0mm
NSR	COOPER TIRES	5.0mm
OSF	MICHELIN	6.0mm
OSR	COOPER TIRES	5.0mm
Spare		

Features

- Bluetooth connection
- Navigation system
- Telephone
- Air conditioning
- Rear electric windows
- Drivers airbag
- Central locking
- Cruise control
- Park assist camera
- Radio/CD
- Climate control
- Rear headrests
- Passenger airbag
- Remote central locking
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim
- Heated front seat
- Rear wiper
- Electric door mirrors
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels

Photos








GX72 XGY


GX72 XGY




Range
P




DAB/FM
UCB 2
Religion
V2 Radio Sussex
Pop
88.3 MHz
100.0 MHz














Condition Check



Damage Photos



1: Wheel osf
Scratched
Over 50mm



2: Door osr
Scratched
UpTo 25mm Thru Paint



3: Door osf
Chipped
Edge Chip




4: Wheel osr
Corroded
Light



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
25 to 100mm Thru Paint



7: Bumper Rear
Chipped
1 To 5



8: Wheel nsr
Scratched
Over 50mm



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



10: Door nsf
Chipped
Edge Chip



11: Wheel nsf
Scratched
Over 50mm



12: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK

EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		

Windows	OK	Radio	OK
Sat nav	OK	Steering	OK