46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

RE64EKJ

Honda CR-V 2.0 i-VTEC EX 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	19/12/2014	**Body Style**	Estate	**Last service miles**	82,446
Year	2014	**Keys**	2	**MOT Due**	18/12/2026
Mileage	124,044 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Printout	**Gears**	6
Colour	BLUE	**Number of stamps**	3	**Doors**	5
VIN	SHSRE5790EU006957	**Last service date**	09/12/2022		

Last Service - 09.12.2022 at 82446 miles (3 main dealer Services)

Tyres

NSF	MICHELIN	4.0mm
NSR	MICHELIN	5.0mm
OSF	MICHELIN	4.0mm
OSR	MICHELIN	5.0mm
Spare		

Features

- Bluetooth connection
- Park assist camera
- Radio/CD
- Air conditioning
- Front electric windows
- ABS
- Tyre pressure monitor
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Body coloured bumpers
- Climate control
- Rear electric windows
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Electric door mirrors
- Electrically adjustable drivers seat
- Rear headrests
- Passenger airbag
- Remote central locking
- Navigation system
- Telephone
- Fixed panoramic glass roof
- Front armrest
- Metallic Paint
- Traction control
- Leather seat trim

Photos

















Eastbourne Car Auctions

Condition Check



Damage Photos



1: Wheel osf
Corroded
Light



2: Wing osf
Chipped
1 To 5



3: A Post os
Chipped
1 To 5



4: Door osf
Chipped
1 To 5



5: Door osf
Chipped
Edge Chip



6: Door osr
Scratched
Over 25mm Thru Paint



7: Wheel osr
Corroded
Light




8: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



9: Bumper Rear
Scratched
Over 100mm Thru Paint



10: Lamp nsr
Broken
Replace



11: Tailgate
Chipped
1 To 5




12: Qtr Panel nsr
Dented
Between 10mm + 30mm




13: Qtr Panel nsr
Chipped
1 To 5



14: Wheel nsr
Corroded
Light



15: Door nsr
Chipped
Multiple Chips



16: Door nsf
Chipped
Multiple Chips



17: Wing nsf
Scratched
UpTo 25mm Thru Paint



18: Wheel nsf
Corroded
Light



19: Bonnet
Chipped
Multiple Chips



20: Bumper Front
Chipped
Multiple Chips

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
Sat nav	OK	Steering	OK