46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

AO59FYB

Vauxhall Astra 1.4i 16V Active 5dr

nama GRADE 4

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	TBC

Details

Reg. date	29/09/2009	**Colour**	BLUE	**MOT Due**	11/12/2026
Year	2009	**VIN**	W0L0AHL48A8006767	**Gearbox**	MANUAL
Mileage	40,046 Miles Warranted	**Body Style**	Hatchback	**Gears**	5
		Keys	1	**Doors**	5
Fuel Type	PETROL				

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	AUTOGRIP	5.0mm
Spare		


Features

- Rear wiper
- Air conditioning
- ABS
- Central locking
- Radio/CD
- Front electric windows
- Drivers airbag
- Remote central locking
- Body coloured bumpers
- Rear headrests
- Passenger airbag
- Cloth seat trim
- Electric door mirrors
- Metallic Paint
- Traction control
- Steel wheels

Photos






Refuel










Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint




2: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osr
Scratched
Over 25mm Thru Paint



5: Qtr Panel osr
Dented
With Paint Damage



6: Bumper Rear
Scratched
Over 100mm Thru Paint



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: Sill ns
Dented
With Paint Damage



9: Door nsr
Chipped
1 To 5




10: Door nsf
Chipped
1 To 5



11: Door Mirror Assy nsf
Scratched (Painted)
UpTo 25mm Thru Paint



12: Wing nsf
Dented
With Paint Damage



13: Bumper Front
Scratched
Over 100mm Thru Paint



14: Bonnet
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer

Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.

Additional fees may apply to some vendors.

Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK