46 Brampton Road
Eastbourne
BN22 9BN
01323 520295 | no-reply@ebca.co.uk

VEHICLE INSPECTION REPORT

OV16KCA

Peugeot 208 1.2 PureTech XS-White 5dr

nama GRADE 5

Inspection

Serious Damage?	No

Vehicle

VAT	Margin
V5	Present

Details

Reg. date	28/04/2016	**Body Style**	Hatchback	**Last service miles**	93,229
Year	2016	**Keys**	2	**MOT Due**	Expired
Mileage	101,000 Miles Warranted	**Service history**	Yes	**Gearbox**	MANUAL
Fuel Type	PETROL	**Service documents**	Service Book	**Gears**	5
Colour	BLUE	**Number of stamps**	7	**Doors**	5
VIN	VF3CCHMZ6GT044570	**Last service date**	28/02/2026		

Last Service - 28.02.2026 at 93229 miles (7 Services)

Tyres

NSF	BUDGET	5.0mm
NSR	BUDGET	5.0mm
OSF	BUDGET	5.0mm
OSR	BUDGET	5.0mm
Spare		

Features


- Bluetooth connection
- Service indicator
- Electric door mirrors
- Front electric windows
- Steering wheel rake adjustment
- ABS
- Side airbags
- Alloy wheels
- Cruise control
- Steering wheel mounted controls
- Front fog lights
- Front head restraints
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- PAS
- Digital radio
- Air conditioning
- Height adjustable drivers seat
- Metallic Paint
- Isofix child seat anchor points
- Remote central locking
- Rear wiper
- Body coloured bumpers
- Folding rear seats
- Rear headrests
- 3x3 point rear seat belts
- Passenger airbag
- Cloth seat trim

Photos














37°c
14:30
Absolute 00s
Repair Point
108(Sussex)
Station 1



Condition Check



Damage Photos



1: Bonnet
Dented
Over 30mm



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Chipped
Multiple Chips




4: Wheel nsf
Scratched
Over 50mm




5: Wing nsf
Chipped
1 To 5




6: Screen Front
Scratched
Over 30mm



7: Door Mirror Assy osf
Scratched (Painted)
UpTo 25mm Thru Paint




8: Door nsf
Dented
With Paint Damage



9: Door nsr
Dented
With Paint Damage



10: Qtr Panel nsr
Dented
With Paint Damage



11: Sill ns
Scratched
Over 25mm Thru Paint



12: Wheel nsr
Scratched
Over 50mm



13: Bumper Rear
Cracked
Over 25mm



14: Qtr Panel osr
Scratched
UpTo 25mm Thru Paint



15: Wheel osr
Scratched
Over 50mm



16: Door osr
Dented
With Paint Damage



17: Door osf
Chipped
1 To 5



18: Door osf
Chipped
Edge Chip



19: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



20: Wheel osf
Scratched
Over 50mm



21: Wing osf
Chipped
1 To 5

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Vehicle Inspection Report

Disclaimer
Photographs, inspection reports and other descriptions are primarily for the use of customers using our LiveBid facility who are not able to attend the sale in person. Those who bid in person must satisfy themselves as to the condition of the vehicle before they bid; we cannot address post-sale issues which rely solely on our reports, descriptions and/or photographs.
Additional fees may apply to some vendors.
Please note buyers rate increase from 01/01/2025

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	Service indicator light illuminated	OK
ABS light illuminated	OK		
Windows	OK	Radio	OK
		Steering	OK